

# **LOC EC Strip Light Series Installation Guide**

# **SAFETY INSTRUCTIONS: Read instructions carefully before attempting to install fixture.**

- All wiring should be performed by a qualified electrician.
- Disconnect power before installing or servicing. This fixture must be wired in accordance with the National Electrical Code and applicable local codes and ordinances.

#### **CAUTION: Risk of fire**

- WARNING: Make certain power is OFF before installing or maintaining fixture. No user serviceable parts inside.
- **WARNING:** Do NOT handle energized fixture when hands are wet, when standing on wet or damp surfaces or in water.
- **WARNING:** Vapor barrier must be suitable for 90°C.
- **WARNING:** Fixture to be independently supported to building structure.

### **CLEANING & MAINTENANCE:**

CAUTION: Be sure the fixture temperature is cool enough to touch. Do NOT clean or maintain while the fixture is energized.

- 1. Clean glass lens with non-abrasive glass cleaning solution.
- 2. Do NOT open fixture to clean the LED. Do NOT touch the LED.

Note: These instructions do not cover all details or variation in equipment, nor do they provide for every possible situation during installation, operation or maintenance.


# **TROUBLESHOOTING:**

- 1. Check that the line voltage at fixture is correct. Refer to wiring directions.
- 2. Check that the fixture is grounded properly.

## 0-10V DIMMABLE WIRING:

Universal voltage driver permits operation at 120V through 347V, 50/60Hz. 0-10V control wires must be rated for 300V minimum. For 0-10V dimming, follow the wiring directions.

- 1. Connect the BLACK fixture lead to the (+) LINE supply lead.
- 2. Connect the WHITE fixture lead to the (-) COMMON supply lead
- 3. Connect the GROUND wire from fixture to the supply ground. Do NOT connect the GROUND of the dimming fixture to the output.
- 4. Connect the VIOLET fixture lead to the (V+) DIM lead.
- 5. Connect the GRAY fixture lead to the (V-) DIM lead.



Phone: (844) LEDONE6 | Fax: 1-510-217-9461 | Web: www.ledonecorp.com

# **LOC EC Strip Light Series Installation Guide**




**INSTALLATION OPTIONS:** 


CAUTION: Turn off electrical power at fuse or circuit breaker box before wiring fixture to the power supply.

#### **CHAIN HANGER**

- 1. Mount chain to ceiling.
- 2. Connect chain to V hanger as pictured below.
- 3. Connect the wiring to the fixture.








#### **SURFACE MOUNT**

- 1. Press the housing on the hole position to open the lens. (Fig. 1)
- 2. Use the fixture as a guide to mark the location for the 4 holes. Put the fixture aside and drill the 4 holes. (Fig. 2)
- 3. Secure the fixture into place with the help of mounting screws (not included). Make sure to pass the junction box cables into the fixture housing. (Fig. 2)
- 4. Connect the fixture wires to the junction box wires. (Fig. 2)
- 5. Place the lens back on. (Fig. 3)







Fig. 3



Phone: (844) LEDONE6 | Fax: 1-510-217-9461 | Web: www.ledonecorp.com